



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	Examiner: A. Patel
MASATO YAMANOBE, ET AL.	:)	
Application No.: 09/041,639	:	Group Art Unit: 2879
Filed: March 13, 1998)	
For: IMAGE-FORMING APPARATUS	;	October 25, 2004
U.S. Patent No. 6,787,983 B2	;	
Issued: September 7, 2004	;	Certificate OCT 2 9 2004
The Honorable Commissioner of Patents and Trademarks		of Correction
P.O. Box 1450 Alexandria, VA 22313-1450		
NGUYEN2 00000110 6787983		

10/26/2004 N

01 FC:1811

100.00 OP

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office

by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Scott D. Malpede

Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDM\mm

DC_MAIN 180811v1

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,787,983 B2

DATED

September 7, 2004

INVENTOR(S) :

MASATO YAMANOBE, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Under (*) Notice, please insert the following:

-- CPA: This patent issued on a continued prosecution application filed under 37 CFR 1.53(d), and is subject to the twenty year patent term provisions of 35 U.S.C. 154(a)(2).--

[56] REFERENCES CITED:

FOREIGN PATENT DOCUMENTS, "JP 31-196455 8/1991" should read --JP 3-196455 8/1991--.

COLUMN 11:

Line 12, "electroconductive" should read --electroconductive film--.

Line 52, "1.3×10⁶ Pa" should read --1.3×10⁻⁸ Pa--.

Line 53, " 1.3×10^8 Pa." should read -- 1.3×10^{-6} Pa.--.

Line 65, "1×10⁵ Pa" should read --1×10⁻⁵ Pa--, and "1.3×10⁶ Pa." should read --1.3×10⁻⁶ Pa--.

COLUMN 20:

Line 39, "image-fanning" should read --image-forming--.

COLUMN 21:

Line 15, "circuit" should read --circuit;--. Line 45, "of sad" should read --said--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 6,787,983 B2

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) (Form#30)

OCT 2 9 2004

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

6,787,983 B2

DATED

September 7, 2004

INVENTOR(S) :

MASATO YAMANOBE, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 22:

Line 2, "envelope," should read --envelope;--. Line 49, "put of" should read --part of--.

DC_MAIN 180805v1


MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,787,983 B2</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,787,983 B2

DATED

September 7, 2004

INVENTOR(S) :

MASATO YAMANOBE, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Under (*) Notice, please insert the following:

-- CPA: This patent issued on a continued prosecution application filed under 37 CFR 1.53(d), and is subject to the twenty year patent term provisions of 35 U.S.C. 154(a)(2).--

[56] REFERENCES CITED:

FOREIGN PATENT DOCUMENTS, "JP 31-196455 8/1991" should read 3-196455 8/1991--. --JP

COLUMN 11:

Line 12, "electroconductive" should read --electroconductive film--.

Line 52, "1.3×10⁶ Pa" should read --1.3×10⁻⁸ Pa--.

Line 53, " 1.3×10^8 Pa." should read -- 1.3×10^{-6} Pa.--.

Line 65, "1×10⁵ Pa" should read --1×10⁻⁵ Pa--, and "1.3×10⁶ Pa." should read --1.3×10⁻⁶ Pa--.

COLUMN 20:

Line 39, "image-fanning" should read --image-forming--.

COLUMN 21:

Line 15, "circuit" should read --circuit;--. Line 45, "of sad" should read --said--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,787,983 B2

No. of add'l. copies @ 30¢ per page



Staple Only! PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

6,787,983 B2

DATED

September 7, 2004

INVENTOR(S) :

MASATO YAMANOBE, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 22:

Line 2, "envelope," should read --envelope;--. Line 49, "put of" should read --part of--.

DC_MAIN 180805v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. 6,787,983 B2

No. of add'l. copies @ 30¢ per page



907 2 3 2004